

Project No. 301159 June 1988

# Analytical Work Plan for Ground Water

Phase I Site Investigation and Analysis Basin F Ground Water Treatment Interim Response Action Contract No. DACW45-88-D-0008



Rocky Mountain Arsenal Commerce City, Colorado Rocky Mountain Arsenal Information Center Commerce City, Colorado

Prepared for:

Department of the Army Corps of Engineers, Omaha District Omaha, Nebraska



This document has been approved for public release and sale; its distribution is unlimited.

19950612 156

Form Approved

REPORT DOCUMENTATION PAGE OMB No. 0704-0188 Public reporting burden for this collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Washington Headquarters Services, Directorate for Information Operations and Reports, 1215 Jefferson Collection of Information, including suggestions for reducing this burden, to Washington Headquarters Services, Directorate for Information, Occasional Project (0704-0188), Washington, DC 20503. 3. REPORT TYPE AND DATES COVERED 2. REPORT DATE 1. AGENCY USE ONLY (Leave blank) 06/00/88 5. FUNDING NUMBERS 4. TITLE AND SUBTITLE PHASE I, SITE INVESTIGATION AND ANALYSIS, BASIN F GROUNDWATER TREATMENT, INTERIM RESPONSE ACTION, ANALYTICAL WORK PLAN FOR GROUNDWATER, ROCKY MOUNTAIN ARSENAL, COLORADO 6. AUTHOR(S) DACW45 88 D 0008 8. PERFORMING ORGANIZATION 7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES) REPORT NUMBER IT CORPORATION ENGLEWOOD, CO 88189R02 10. SPONSORING/MONITORING 9. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(ES) AGENCY REPORT NUMBER ARMY CORPS OF ENGINEERS. OMAHA DISTRICT COMMERCE CITY, CO 11. SUPPLEMENTARY NOTES 12b. DISTRIBUTION CODE 12a. DISTRIBUTION/AVAILABILITY STATEMENT APPROVED FOR PUBLIC RELEASE; DISTRIBUTION IS UNLIMITED 13. ABSTRACT (Maximum 200 words) THIS SAMPLING AND ANALYSIS PLAN IS FOR THE GROUND WATER SAMPLES TO BE COLLECTED FROM THE SIX MONITORING WELLS LOCATED NORTH OF BASIN F. THE PLAN CONTAINS INFORMATION ON THE FOLLOWING: 1. PURGING OF THE WELLS

- 2. MEASUREMENT OF FIELD PARAMETERS
- 3. SAMPLE COLLECTION
- 4. SAMPLE PRESERVATION AND HANDLING
- 5. CHAIN-OF-CUSTODY CONTROL
- 6. ANALYTICAL PROCEDURES
- 7. FIELD AND LABORATORY QUALITY ASSURANCE/QUALITY CONTROL.

DTIC QUALITY INSPECTED ?

14. SUBJECT TERMS			15. NUMBER OF PAGES
QA/QC PLAN, SAMPLING		•	16. PRICE CODE
17. SECURITY CLASSIFICATION OF REPORT	18. SECURITY CLASSIFICATION OF THIS PAGE	19. SECURITY CLASSIFICATION OF ABSTRACT	20. LIMITATION OF ABSTRACT
IINCI ASSIETED			

# ANALYTICAL WORK PLAN FOR GROUND WATER PHASE I SITE INVESTIGATION AND ANALYSIS BASIN F GROUND WATER TREATMENT INTERIM RESPONSE ACTION ROCKY MOUNTAIN ARSENAL, COLORADO

# Prepared for:

Department of the Army Corps of Engineers, Omaha District Contract Number DACW45-88-D-008 Accesion For

NTIS CRA&I DIDIC TAB DIDIC TAB DIDIC TAB DIDICITAB DIDICITA DIDICITAB DIDICITA DIDICITAB DIDICITAB DIDICITAB DIDICITAB DIDICITAB DIDICITAB DIDICITA DI DIDICITA DIDICITA DI DIDICITA DI DIDICITA DI DIDICITA DIDICITA DI DIDIC

# Prepared by:

IT Corporation Project Number 301159.01.01

Prepared by Analytical Chemis	t Date:	123/88
Approved by June W Ospanion Office Of	Date:	
Approved by Project Manager	Date:	6/28/88
Approved by William Project Director	Date:	6/28/88
Approved by General Manager	Date:	6/29/88
Approved byArmy Corps of Enginee	Date:	

COE:-COM002429

# TABLE OF CONTENTS

		<u>P.</u>	AGE
LIST	OF T	ABLESi	li
LIST	OF F	IGURESi	li
1.0	INTRO	ODUCTION	1
2.0	GROUN	ND WATER SAMPLING	1
	2.1	MEASUREMENT OF ORGANIC VAPORS AT THE BREATHING ZONE	1
	2.2	MEASUREMENT OF STATIC WATER LEVELS	1
	2.3	DETECTION OF IMMISCIBLE LAYERS	2
	2.4	WELL EVACUATION	2
	2.5	SAMPLE COLLECTION	3
		2.5.1 SAMPLE PRESERVATION AND HANDLING	4
		2.5.2 DECONTAMINATION PROCEDURES FOR NON-DEDICATED EQUIPMENT	4
	2.6	CHAIN OF CUSTODY	4
	2.7	FORM COMPLETION AND RECORD MAINTENANCE	5
3.0	ANAL	YTICAL PROCEDURES/PROTOCOLS	5
	3.1	FIELD AND LABORATORY QUALITY ASSURANCE/QUALITY CONTROL	6
		3.1.1 FIELD QA/QC PROGRAM	6
		3.1.2 LABORATORY QA/QC PROGRAM	6
4.0	REQU:	IRED PLANS AND REPORTS	7
	4.1	A-E QUALITY CONTROL PLAN (A-E QCP)	7
	4.2	A-E QUALITY MANAGEMENT PLAN (A-E LAB QMP)	7
	4.3	A-E DAILY QUALITY CONTROL REPORT (A-E DQCR)	7
	4.4	A-E QUALITY CONTROL SUMMARY REPORT (A-E QCSR)	8
5.0	EVAL	UATION OF THE QUALITY OF GROUND WATER CHEMICAL DATA	8
TABLE	ES		
FIGUE	RES		
APPE	NDIX	A - TABLE OF CONTENTS FROM LABORATORY SPECIFIC ATTACHMENT (IT-Expo	ort)

# LIST OF TABLES

TABLE NO.	TITLE
1	Ground Water Sampling Specifications for Basin F (IT-Export Samples)
2	Analytical Parameters /Compounds for Basin F Ground Water Monitoring Program to be Analyzed by Government Laboratory
3	Ground Water Analytical Specifications (IT-Export) for Basin F Ground Water Samples

# LIST OF FIGURES

FIGURE NO.	TITLE
1	Sample Label
2	Ground Water Sample Collection Log
3	Chain of Custody Record
4	Request for Analysis
5	Daily Quality Control Report

### 1.0 INTRODUCTION

This sampling and analyses plan is for the ground water samples to be collected from the six monitoring wells located north of Basin F at the Rocky Mountain Arsenal. This plan contains information regarding the following:

- Purging of the well
- Measurement of field parameters
- · Sample collection
- · Sample preservation and handling
- · Chain of custody control
- · Analytical procedures
- · Field and laboratory quality assurance/quality control

# 2.0 GROUND WATER SAMPLING

Ground water from the six wells will be collected by the Program Manager--Rocky Mountain Arsenal, Technical Operations Division (PM-RMA, TOD) representatives for analyses of the parameters listed on Table 1. Table 1 parameters will be analyzed by the A-E contract laboratory, IT Analytical Services, Export, PA, while Table 2 parameters will be analyzed by the government laboratory. Details of sampling and analytical parameters for the government analyzed samples are addressed in the Rocky Mountain Arsenal, Comprehensive Monitoring Program, Ground Water Monitoring Technical Plan.

# 2.1 MEASUREMENT OF ORGANIC VAPORS AT THE BREATHING ZONE

The air in the well head as well as in the breathing zone will be measured immediately after the unlocking of the well for organic vapors using a organic vapor analyzer such as an HNu, photo-ionization detector. This information will be useful for Health and Safety protection requirements as well as an indicator of the possible presence of light phase immiscible layers floating in the well. The Safety, Health and Emergency Response Plan (SHERP) details the level-of-protection requirements for the concentration of organic vapors that may be encountered during the sampling process.

# 2.2 MEASUREMENT OF STATIC WATER LEVELS

Water level measurements will be taken before the purging of the well using a water level tape or electrical well sounder. The depth to standing water as well as the total depth of the well will be determined. This information is

required to calculate the volume of water in the well casing and provides a check on the integrity of the well (i.e., identifies any silting problems). These measurements will be determined to the nearest 0.01 foot. Each well will have a permanent, easily identifiable reference point from which water level and depth of well measurements can be obtained. The well identifier will also be indelibly marked on the well for identification.

# 2.3 DETECTION OF IMMISCIBLE LAYERS

A clear bailer will be used to determine the presence of any "sinkers" or "floaters" in the stagnant well water. "Sinkers" are those relatively insoluble organic liquids which are more dense than water and tend to migrate toward the bottom of the well bore. "Floaters" are those relatively insoluble organic liquids that are less dense than water and that tend to occur at the water table. IT will provide a clear bailer to the PM-RMA, TOD for their use in the detection of these layers. The bailer will be first lowered slightly below the stagnant water layer and gently removed from the well and examined for an immiscible phase. The process will be repeated for the detection of potential sinking phases by carefully lowering the bailer to the bottom of the well screen and removing it to examine it for an immiscible phase. The sampling team shall make note of the approximate thickness of each layer if they are present.

# 2.4 WELL EVACUATION

The water standing in a well prior to sampling may not be representative of the in situ ground water quality. Therefore the sampling team must remove the standing water in the well and filter pack so that formation water can replace the stagnant water. Each well will be purged using a bailer, bladder pump or air-driven piston pump for a minimum of three well casing volumes; purging is then continued until the field parameters have stabilized to within 10 percent of the previous values. Field parameters will be measured a minimum of three times, i.e., after each well bore volume. If the field parameters have stabilized after the purging of three well casings, sampling may begin. The field parameters to be measured are temperature, pH, and specific conductance. The pH and specific conductance instruments will be standardized at least daily. Field parameters will be measured after the samples for laboratory analyses have been collected to ensure that the ground water parameters have remained

stable during sample collection. In cases where the well recovers slowly such that three well bore volumes cannot be removed before the well is evacuated to dryness, the sampling team will purge to dryness. Once the well has recovered sufficiently to allow collection of all the samples necessary for laboratory analyses, the sampling process will begin. Measures shall be taken to prevent surface soils from coming in contact with the purging equipment and lines, which in turn could introduce contaminants to the well. Purged water should be collected and drummed for proper disposal.

# 2.5 SAMPLE COLLECTION

The technique used to withdraw a ground water sample from a well is based on the considerations of the parameters to be analyzed in the sample. To improve the degree to which the ground water sample is representative of the formation, it is important to minimize physically altering or chemically contaminating the sample during the sampling process.

Samples for laboratory chemical analyses will be collected in the order of decreasing volatile sensitivity of the parameters as follows:

Volatile Organic Compounds (VOA)
Extractable Organics (BNAs, Pesticides)
Total Metals
Dissolved Metals
Sulfate and Chloride
Turbidity
Nitrate and Ammonia

Temperature, pH, and specific conductivity measurements shall be made in the field during the purging activity, and before and after the ground water samples are collected. At the conclusion of sampling each well, the sampling device shall be decontaminated. At no time will a sampling device that has not been decontaminated be introduced into the well. Section 2.5.2 discusses the decontamination procedures in detail.

If pumping is used to collect the sample for volatile organic compounds the pumping rate should not exceed 100 milliliters per minute. Higher pumping rates can increase the loss of volatile constituents and can cause fluctuations in the pH value and pH sensitive analytes. When the volatile samples have been collected the pumping rate may be increased but at no time should it exceed the pumping rate used during the purging process.

# 2.5.1 Sample Preservation and Handling

Many of the chemical constituents and physicochemical parameters that are to be analyzed or evaluated are not chemically stable, therefore sample preservation is required. Table 1 lists the preservatives and containers to be utilized for the parameters to be analyzed by IT-Export. IT will provide containers and labels for Table 1 samples. As indicated in Table 2, the containers and preservatives for the government-operated laboratory samples will be in accordance with the Rocky Mountain Arsenal Comprehensive Monitoring Program, Ground Water Monitoring Technical Plan. Samples collected for volatile organic analyses will be collected in 40-ml amber glass vials using teflon-septum lined caps. Samples for volatiles should be transferred from the sampling device taking care to minimize volatilization. Sample containers will be sealed with no headspace present. Total organic carbon samples should be handled and analyzed as materials containing volatile organics. No headspace should exist in the sample containers at the time of receipt by the laboratory, as well as at the time the sample was collected. Ground water samples for metal analyses will be field filtered through a 0.45 micron membrane filter and transferred to a bottle containing the nitric acid for preserving the sample. Particles must be filtered out since they may absorb or adsorb various ionic species and effectively lower the dissolved metal content in the well water.

# 2.5.2 Decontamination Procedures for Non-Dedicated Equipment

All non-dedicated sampling and measuring equipment shall be decontaminated before introduction into a well. Decontamination will consist of a deionized water rinse followed by washing with a non phosphate detergent and a second rinse with deionized water. Following this washing a methanol rinse followed by another deionized rinse shall be performed. This procedure applies to all sampling equipment as well as water level/well sounding equipment and field measuring devices.

# 2.6 CHAIN-OF-CUSTODY

An adequate chain-of-custody shall allow for the tracing of possession and handling of the individual samples from the time of sample collection through laboratory analyses. All chain-of-custody and water sample collection infor-

mation shall be recorded completely and transferred to IT Corporation personnel with the samples to be shipped to the IT Laboratory. Copies of all paperwork regarding the samples shipped to the government laboratory will be transferred to IT Corporation personnel at this time. Key elements of the chain-of-custody procedure include:

- sample labels--prevents misidentification of samples (Figure 1)
- sample seals (custody tape)--provides evidence that the sample has been unopened until time of laboratory analyses
- water sample collection log--provides information on the collection of the sample and its physicochemical condition upon collection (Figure 2)
  - chain-of-custody record--establishes the documentation necessary to trace sample possession from the time of collection to analyses (Figure 3)
- request-for-analysis--serves as the official "work order" explaining the analytical program to the laboratory, for each sample (Figure 4).

# 2.7 FORM COMPLETION AND RECORDS MAINTENANCE

All forms shall be completed, addressing each item on the form. If a particular item is not applicable to the work performed, a line or N/A will be used to indicate this. All records will be filed at the IT-Englewood office in accordance with the standard IT filing system as described in the IT QA Manual.

# 3.0 ANALYTICAL PROCEDURES/PROTOCOLS

Table 3 outlines the analytical procedures for the analyses of samples to be analyzed by IT-Export. The procedures are EPA-approved methods and are suitable analytical methods for the samples collected. Table 3 also provides expected precision and accuracy values for the methods presuming that the collected water does not have matrix interference problems. It should be noted that these procedures do not necessarily apply to the government laboratory analytical protocol since the government laboratory procedures are governed by USATHAMA QA/QC procedures.

# 3.1 FIELD AND LABORATORY QUALITY ASSURANCE/QUALITY CONTROL

The establishment of a sound quality assurance/quality control (QA/QC) program is of utmost importance to ensure the reliability and validity of the field and analytical laboratory data gathered as part of the overall ground water monitoring program.

# 3.1.1 Field QA/QC Program

Two types of field QA/QC samples will be collected as part of the ground water sampling program: field equipment rinsate blanks and field duplicates. samples will be collected by the PM, RMA TOD. IT will supply containers and labels for the QA/QC samples which relate to the samples to be analyzed by IT. The equipment rinsate blank will only be collected for the metals analyses. A field duplicate will be collected for all the parameters to be analyzed. The equipment rinsate blank is collected to document the cleanliness of the nondedicated sampling device. This sample is collected from the final rinsate after deconning the sample collection device. If this analysis shows contamination, the results of this analysis will not be used to correct the ground water data (i.e., subtracted from any positive results). The source of the contamination would be identified and corrective action, including possible resampling as an option, can be initiated. The field duplicate shall be analyzed for all the same parameters as its common sample. A fictitious sample designation is assigned to the duplicate to provide a "blind" sample to the laboratory. This provides a check on the laboratory precision as well as a check of the field collection reproducibility. The error associated with either field or laboratory reproducibility cannot be distinguished if this samples identity is disguised. It should be emphasized that data from QC samples should be used as a measure of performance or as an indicator of potential sources of cross-contamination, but should not be used to alter or correct analytical data.

# 3.1.2 Laboratory QA/QC Program

The laboratory QA/QC program is detailed in two documents. IT Analytical Services Quality Assurance Manual and the supplemental Laboratory Specific Attachment for the IT-Export laboratory. The laboratory-specific attachment defines more clearly specific details discussed in the corporate IT QA Manual such as calibration practices and reporting procedures. It is recognized that

some quality assurance practices vary in each of the IT laboratories, therefore, the lab-specific attachment is used as a supplement to the corporate ITAS <u>Quality Assurance Manual</u>. Appendix A is a reproduction of the Table of Contents from the IT-Export laboratory specific attachment to the IT Corporate QA manual. QA/QC requirements for the PM, RMA TOD laboratory analyses are presented in the Rocky Mountain Arsenal Comprehensive Monitoring Program, Ground Water Monitoring Technical Plan.

# 4.0 REQUIRED PLANS AND REPORTS

These are required plans and reports for this phase of work that adequately document quality aspects of the work.

# 4.1 A-E QUALITY CONTROL PLAN (A-E QCP)

The A-E QCP is a working document that outlines the respective COE and A-E quality control related responsibilities for this project. This Analytical Plan for water serves that purpose.

# 4.2 A-E QUALITY MANAGEMENT PLAN (A-E Lab QMP)

The A-E Lab QMP is an "off-the-shelf" brochure which describes the laboratories personnel qualifications, equipment, analytical capabilities, quality control program, and other related topics specific to the functioning of the laboratory. Two documents function as the IT-Export QMP. These documents are the ITAS <u>Corporate Quality Assurance Manual</u> and the laboratory-specific attachment for the IT-Export laboratory. A copy of the outline of the laboratory specific attachment is provided in Appendix A.

# 4.3 A-E DAILY QUALITY CONTROL REPORT (A-E DQCR)

The A-E DQCR is a report documenting daily project activities submitted to the PM-COE at regular intervals. The A-E DQCR will be completed throughout the duration of the on-site sample collection and/or field analysis period. An example of the form to be utilized for the DQCR is provided as Figure 5 in this plan.

# 4.4 A-E QUALITY CONTROL SUMMARY REPORT (A-E QCSR)

The A-E QCSR is a report that will be submitted at the conclusion of the sampling and analyses period that summarizes the results of the Daily Quality Control Reports, A-E laboratory analyses and associated quality control samples. Information presented will be a tabular summary of the data, raw data and any observations made relating to the obtained data.

# 5.0 EVALUATION OF THE QUALITY OF GROUND WATER CHEMICAL DATA

The ground water sampling and analyses program produces a variety of ground water chemical constituent data. The chemical data may be presented in a data summary package in tabular and graphical forms. Tabular formats may be as simple as presenting the data as it is received from the analyzing laboratory. Summaries of the laboratory data may aid in its interpretation. Graphical presentations of data can aid in the interpretive process and may also be used. All tabulations of data must be accompanied by an explanation assessing its validity, completeness, representativeness and accuracy. Any data gaps, QC problems or deviations in detection limit and precision should be addressed in the data summary package.

TABLE 1

GROUND WATER SAMPLING SPECIFICATIONS FOR BASIN F

(IT-EXPORT SAMPLES)

PARAMETER	CONTAINER	SAMPLE PRESERVATION	HOLDING TIME
Dissolved Solids (Total)	1-liter glass bottle filtered on site	Ice to 4°C	Analyze in 7 days
Organic Carbon (Total)	1-liter glass bottle	Acidify to ph < 2 (HCl) Ice to 4°C	Analyze in 28 days
Total Metals	1-liter high density polyethylene bottle	Acidify to pH $< 2$ (1:1 HNO <sub>3</sub> )	6 months
Ammonium	1-liter glass bottle	$\rm H_2SO_4$ to ph < 2 Ice to $\rm 4^{\circ}C$	Analyze in 28 days
Silica, Dissolved	200 ml. high density polyethylene bottle	Ice to 4°C	Analyze in 28 days
Bicarbonate	200 ml. glass bottle	Ice to 4°C	Analyze in 14 days

RMA/BSNFGWAP-1 6/13/88

### TABLE 2

# ANALYTICAL PARAMETERS/COMPOUNDS FOR BASIN F GROUND WATER MONITORING PROGRAM TO BE ANALYZED BY GOVERNMENT LABORATORY

# METALS/ICP/AA

Zinc

# ANIONS/GENERAL CHEMISTRY

Alkalinity Arsenic Chloride Cadmium Conductivity Calcium Fluoride Chromium Nitrate Copper Nitrite Lead Sulfate Magnesium рΗ Mercury Potassium Sodium

# ORGANOCHLORINE PESTICIDES (GCECD)

Aldrin
Dieldrin
Endrin
Hexachlorocyclopentadiene (HCCP)
Isodrin
2,2-bis(para-chlorophenyl)-1,1-Dichloroethane (P,P'-DDE)

# SEMIVOLATILE ORGANIC COMPOUNDS (GCMS)

Dibromochloropropane (DBCP)
Dicyclopentadiene (DCPD)
Diisopropylmethylphosphate (DIMP)
Dimethylmethylphosphonate (DMMP)

# ORGANOSULFUR COMPOUNDS (GCFPD)

Chlorophenylmethylsulfide (PCPMS)
Chlorophenylmethylsulfone (PCPMSO)
Chlorophenylmethylsulfoxide (PCPMSO2)
Dithiane
1,4-Oxathiane

# TABLE 2 (Continued)

# VOLATILE ORGANIC COMPOUNDS (GCPID)

Benzene Ethylbenzene M-xylene O- and P-xylene Toluene

# VOLATILE HALOGENATED ORGANIC COMPOUNDS (GCCON/GCHALL)

1,1-Dichloroethane
1,1-Dichloroethane
1,2-Dichloroethane
1,1,1-Trichloroethane
1,1,2-Trichloroethane
Trichloroethene
Tetrachloroethene
Carbon Tetrachloride
Chlorobenzene
Chloroform
Methylene chloride

# SAMPLING AND PRESERVATION REQUIREMENTS

(Refer to the Rocky Mountain Arsenal Comprehensive Monitoring Program, Ground Water Monitoring Technical Plan.)

TABLE 3

GROUND WATER ANALYTICAL SPECIFICATIONS (IT EXPORT)
FOR BASIN F GROUND WATER SAMPLES

PARAMETER	METHOD NUMBER	EXPECTED DETECTION LIMIT	EXPECTED PRECISION
Dissolved Solids	160.1	10 mg/l	±20%
Organic Carbon	415.1	1 mg/l	±20%
Total Metals	200.7	Iron 0.025 mg/l Manganese 0.015 mg/l Nickel 0.040 mg/l	±20% ±20% ±20%
Ammonium	350.2	0.05  mg/l	±20%
Silica	Lachat Method No. 10-114-27-1-A	0.01 mg/l	±20%
Bicarbonate	310.1	1 mg/l	±20%

INTERNATIONA TECHNOLOGY CORPORATION	SOIL SAMPLE	H → R
Project Name		
Project No.		
Sample No.		<del></del> i
Collection Date/Time		
Collector's Name		·
Sample Location	Boring No	
Depth Sampled		
Sample Type	Undisturbed	
Blow Count	Recovery	
		634-3-88



Project No. : \_\_\_\_\_

Project Name: \_



# GROUND WATER SAMPLE COLLECTION LOG

Sample No. : \_

Sample Location or : \_\_\_\_\_

Well I.D. (attach map if necessary)

Peguest-for-	Analysis Cont	rol No.:			We	ell I.D. (att	ach map if	necessar	y )
	ustody Contro				Da	te and Tin	ne Collect	ed :	
Chameon	23,00y 00 v				Sa	imple Colle	cted By :		
EQUIPMEN'	<u>T</u>								
	Method/Equi								
Sampling	g Equipment							-	
Filtering	Equipment:								
	Equi	pment Cal	ibratio	on .		ŗ		ρН	
EQUIPME	NT MODEL	SERIAL	NO.	DATE	CALIBRAT	ED	STANDARD		
				ļ <del></del>		<u> </u>	TEMP	READING	READING
								NDUCTIVI	TV 1
								STAND	
Other Ca	libration (e.g.	D.O., eH):					TEMP	READI	
							ł		
FIELD PAR	AMETERS	iture ( ): .			_ `S	ampling Se	pth():		
Air Tem	perature (	):			Initial De	epth to Wat	er ( ):		
	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,					eference Po			
	ance ( µmhos /c					d to 25°C (	Y/N)	)	
	Phase (Y/N)_								(
SAMPLE	PACKAGING							Others	
Chemical Group	VOC Including Diethylether & Tetrahyrofuran	General * Chemical Parameters	BNA'	Pest & PCBs	Dissolved Metals (Filtered)	Metals	d)		
Preservative	4°c	Æ	4°c	48	HNOs 46	Æ			
Container	Class	Plastic	Glass	Glass	500ml. Wide	Polyethylene			
Туро	Glass 2x 40ml	1 Liter	1 Gal.	1 Gal.	Mouth Poly- ethylene	1 Liter	<b>'</b>		
& Volume	2× 40m1	, 51191			ethyléne	, 61.01	+ +		
Sampled (Y/N)					·				
* Ammonia a	and Sulfite are r	ot included.							



# CHAIN-OF-CUSTODY RECORD

R/A Control No. \_\_

 $\text{C/C Control No} \, 15207$ 

PROJECT NAME/NUMBER	ME/NUMBER		LAB DESTINATION	INATION		
SAMPLE TEAM MEMBERS	A MEMBERS		CARRIER/	CARRIER/WAYBILL NO		
Sample	Sample Location and Description	Date and Time Collected	Sample Type	Container Type	Condition on Receipt (Name and Date)	Disposal Record No.
•						
Special Instructions:	tions:					
Possible Sample Hazards:	ele Hazards:					
SIGNATURES	SIGNATURES: (Name, Company, Date and Time)					
1. Relinquished By:	id By:		3. Relinquished By:	iished By:		
Received By:	γ.		Received by:	ed by:		
2. Relinquished By:	id By:		- 4. Relinquished By:	lished By:		
Received By:	λ:		- Received By:.	ed By:		

FIGURE 3



# **REQUEST FOR ANALYSIS**

	5	
	<u>.</u>	
	R/A Control No.	C/C Control No.
,	B/A (	2/2

DATE SAMPLES SHIPPED	LAB DESTINATION	SEND LAB REPORT TO	DATE REPORT REQUIRED PROJECT CONTACT	PROJECT CONTACT PHONE NO.
PROJECT NAME	PROJECT NUMBER	PROJECT MANAGER BILL TO	PURCHASE ORDER NO.	

Special Instructions						
Requested Testing Program		r				
Preservative	~					
Sample Volume						
Sample Type						
Sample No.						

(Rush must be approved by the Project Manager.) TURNAROUND TIME REQUIRED:

(Subject to rush surcharge)
Rush
Normal

(Please indicate if sample(s) are hazardous materials and/or suspected to contain high levels of hazardous substances) POSSIBLE HAZARD IDENTIFICATION:

Highly Toxic	
Skin irritant	
Flammable	
Nonhazard	

(Please Specify)

(Please indicate disposition of sample following analysis. Lab will charge for packing, shipping, and disposal.) SAMPLE DISPOSAL:

Disposal by Lab	
sturn to Client	
æ	

FOR LAB USE ONLY

Received By

Date/Time

WHITE - Original, to accompany samples YELLOW - Field copy



DATE:	PROJECT NAME: PROJECT NUMBER: SHEET OF
WEATHER	
TempWind Velocity/Direction	PrecipitationOther
WORK PERFORMED:	
SAMPLING PERFORMED: (Type, local	tion, etc.)
SAMPLES COLLECTED: (Numbers, and	alysis, etc.)
FIELD ANALYSIS PERFORMED: (Typ	e, etc.)
PROBLEMS ENCOUNTERED/CORRECTIV	VE ACTIONS:
QUALITY CONTROL ACTIVITIES IN calibration, etc.)	ITIATED: (e.g., Blanks, duplicates,
Personnel On-site	Important Telephone Calls
ref solitier on-side	
Visitors	
Field Engineer (Print)	Signature

FIGURE 5

6/9/88

RMA/DQCR

# APPENDIX A

TABLE OF CONTENTS FROM LABORATORY SPECIFIC ATTACHMENT (IT-EXPORT)



Section No. PO.0 Revision No.: 0

Date: April 5, 1988

Page 2 of 9

# PITTSBURGH LAB-SPECIFIC QA MANUAL

# TABLE OF CONTENTS

SECTION	SECTION TITLE	SECTION/PAGE
PO.0	TITLE PAGE	0/0
PO.0	TABLE OF CONTENTS	0/2-5
PO.0	LIST OF TABLES	0/6
PO.0	LIST OF FIGURES	0/7-9
P1.0	INTRODUCTION	1/1
	P1.1 OBJECTIVES OF THE QUALITY ASSURANCE PROGRAM	1/1-2
	P1.2 FORMAT OF THE ATTACHMENT	1/3
	P1.3 DOCUMENT CONTROL, DISTRIBUTION, AND REVISION	1/3-4
P2.0	LABORATORY ORGANIZATION	2/1
	P2.1 ITAS-QUALITY RELATED RESPONSIBILITIES WITHIN THE LABORATORY	2/1-3
P3.0	STANDARD LABORATORY PRACTICE	3/1
P4.0	MATERIAL PROCUREMENT AND CONTROL	4/1
	P4.1 REQUIREMENTS FOR REAGENTS, SOLVENTS AND GASES	4/1
	P4.1.1 Inorganic Analysis	4/1
	P4.1.2 Organic Analysis	4/2
	P4.2 WATER	4/2
	P4.3 COMPRESSED AIR	4/2
	P4.4 STORING AND MAINTAINING REAGENTS	4/3
	P4.5 BOTTLE PREPARATION REQUIREMENTS	4/3
	P4.6 GLASSWARE CLEANING REQUIREMENTS	4/3
P5.0	SAMPLE RECEIPT AND INITIATION OF TESTING PROGRAM	5/1
	P5.1 LABORATORY SAMPLE RECEIPT	5/1-2
	P5.1.1 Chain-of-Custody Record	5/2-4
	P5.1.2 Request for Analysis Record	5/4
	P5.2 LABORATORY STORAGE OF SAMPLES	5/4
	P5.3 INITIATION OF TESTING PROGRAM	5/4-5
	P5.3.1 Review of Completed Log-In Forms	5/5
	P5.4 SAMPLE PREDISPOSAL	5/6
	P5.4.1 Sample Storage	5/6
	P5.4.1.1 Predisposal	5/6



Section No. PO.0 Revision No.: 0

Date: April 5, 1988 Page 3 of 9

# TABLE OF CONTENTS (CONTINUED)

SECTION	SECTION TITLE	SECTION/PAGE
	P5.4.1.2 Laboratory Waste Generation	5/6
	P5.4.2 Segregation of Waste	5/6
	P5.4.2.1 Return to Client	5/7
	P5.4.2.2 Combustible Waste	5/7
	P5.4.2.3 Aqua Scrub System	5/7
	P5.4.2.4 Chemical Landfill Disposal	5/7-8
P6.0	CALIBRATION PROCEDURES	6/1
P7.0	PREVENTIVE MAINTENANCE	7/1
P8.0	ANALYSIS OF QUALITY CONTROL SAMPLES	8/1
	P8.1 VOA HOLDING BLANK ANALYSES	8/1
	P8.1.1 VOA Matrix Spike Analyses	8/1
	P8.1.2 Post-Digestion Matrix Spike Analyses	8/1
	P8.1.3 Independent Calibration Verification Sample Analyses	8/2
	P8.2 LABORATORY PERFORMANCE PROGRAMS	8/2
P9.0	ANALYTICAL PROCEDURES	9/1
	P9.1 SAMPLE PREPARATION	9/1-2
	P9.2 INSTRUMENT CALIBRATION	9/2
	P9.3 PREVENTIVE MAINTENANCE	9/2
	P9.4 ANALYTICAL METHODS	9/2
	P9.5 VARIANCE FROM STATED ANALYTICAL METHODS	9/2
	P9.6 DATA SHEETS	9/2
	P9.7 ROUNDING PROCEDURE	9/3
P10.0	DATA VERIFICATION	10/1
	P10.1 PROCESSING OF QUALITY CONTROL DATA	10/1
	P10.2 DATA VALIDATION	10/1-2
	P10.2.1 Group Specific Data Validation	10/3
	P10.2.1.1 GC/MS Compound Identification Criteria	10/3
	P10.2.1.2 GC Compound Identification Criteria	10/4
	P10.2.2 Data Validation Process	10/4-5



Section No. P0.0 Revision No.: 0

Date: April 5, 1988

Page 4 of 9

# TABLE OF CONTENTS (CONTINUED)

SECTION	SECTION TITLE	SECTION/PAGE
	P10.3 VERIFICATION OF SOFTWARE	10/5
P11.0	DATA REPORTS	11/1-2
P12.0	RECORDS MANAGEMENT	12/1
	P12.1 PROJECT RECORDS	12/1-3
	P12.1.1 File Index and File Maintenance	12/3-4
	P12.2 GENERAL LABORATORY OPERATIONS RECORDS	12/2
	P12.3 CERTIFICATION PROGRAM RECORDS	12/4
	P12.4 QUALITY RECORDS	12/5
P13.0	NONCONFORMANCES AND CORRECTIVE ACTION	13/1
	P13.1 IDENTIFICATION AND DOCUMENTATION OF NONCONFORMANCE	13/1
	Pl3.1.1 Internal	13/1
	P13.1.2 External	13/1-2
	P13.2 CORRECTIVE ACTION	13/2
	P13.2.1 Examples of Corrective Action	13/2
	P13.2.2 Follow-Up	13/2
	P13.3 NONCONFORMANCE CLOSE-OUT	13/2
P14.0	QUALITY ASSURANCE/QUALITY CONTROL AUDITS	14/1
	P14.1 IN-HOUSE AUDIT	14/1
	P14.1.1 Monthly Surveillance	14/1
	P14.1.2 Semi-Annual Internal Audits	14/1
	P14.1.2.1 Audit Independence	14/1
	P14.1.2.2 Scheduling	14/1-2
	P14.1.2.3 Audit Preparation	14/2
	P14.1.2.4 Audit Performance	14/2
	P14.1.2.5 Audit Report	14/2-3
	P14.1.2.6 Corrective Action and Follow-Up	14/3
	P14.1.2.7 Audit Records	14/3
	P14.2 SYSTEM AUDITS	14/1
	P14.3 EXTERNAL	14/3



Section No. PO.0 Revision No.: 0

Date: April 5, 1988 Page 5 of 9

# TABLE OF CONTENTS (Continued)

SECTION	SECTION TITLE	SECTION/PAGE
	P14.4 AUDIT RECORDS	14/2
P15.0	QUALITY CONTROL REPORTS TO MANAGEMENT	15/1
P16.0	LABORATORY TRAINING PROGRAMS	16/1
	P16.1 QUALITY ASSURANCE TRAINING	16/1
	P16.2 TECHNICAL TRAINING	16/1



Section No. PO.O Revision No.: 0

Date: April 5, 1988 Page 6 of 9

# LIST OF TABLES

TABLE	NO.	TITLE	SECTION/PAGE
P3-1		Systems Outline-Pittsburgh Laboratory Operations	3/2-4
P5-1		Sampling and Preservation Requirements	5/9-14
P6-1		Summary of Calibration Requirements - Pittsburgh Laboratory Operations	6/2-5
P7-1		Preventive Maintenance Requirements - Pittsburgh Laboratory Operations	7/2-10
P8-1		Quality Control Samples	8/3-5
P9-1		List of Approved Sample Preparation Techniques for Water and Waste Samples	9/4
P9-2		List of Approved Sample Preparation Techniques for Solid Waste Samples	9/5
P9-3		Analytical Test Methods	9/6-24



Section No. PO.0 Revision No.: 0

Date: April 5, 1988 Page 7 of 9

# LIST OF FIGURES

FIGURE NO.	TITLE	SECTION/PAGE
P2-1	ITAS Pittsburgh Laboratory Organizational Chart	2/4
P3-1	Laboratory Analysis Flow Chart	3/5
P5-1	Chain-of-Custody Record Form	5/15
P5-2	Internal Chain-of-Custody Form	5/16-17
P5-3	Request for Analysis Form	5/18
P5-4	Project Sample Log-In Form (Water and Wastewater)	5/19
P5-5	Project Sample Log-In Form (Soils and Solid Waste)	5/20
P7-1	Preventive Maintenance Schedule	7/11
P9-1	Organic Extraction Sheet	9/25
P9-2	GC Screen Data Sheet	9/26
P9-3	New Standard Verification Form	9/27
P9-4	Retention Time Window Form	9/28
P9-5	Continuing Breakdown Check Form	9/29
P9-6	GC Autosampler List	9/30
P9-7	GC Standard Calculation Worksheet	9/31
P9-8	GC Analysis Worksheet	9/32
P9-9	GC Raw Data Print-Out	9/33
P9-10	Computer Generated GC/MS Tuning and Mass Calibration Form (DFTPP)	9/34
P9-11	Computer Generated GC/MS Tuning and Mass Calibration Form (BFB)	9/35
P9-12	GC/MS Standard Calibration Worksheet	9/36
P9-13	GC/MS Analysis Worksheet	9/37
P9-14	Computer Generated Raw Data Form	9/38-43
P9-15	Sulfide Worksheet	9/44
P9-16	Spectrophotometric Analysis Worksheet	9/45
P9-17	Infrared Spectrophotometric Analysis Worksheet	9/46
P9-18	Specific Ion Analysis Worksheet	9/47
P9-19	Specific Conductance Worksheet for Deionized Water	9/48



Section No. PO.O Revision No.: 0

Date: April 5, 1988

Page 8 of 9

# LIST OF FIGURES (CONTINUED)

FIGURE NO.	TITLE	SECTION/PAGE
P9-20	Specific Conductance Worksheet	9/49
P9-21	Residue (Solids) Worksheet	9/50
P9-22	Quality Control Summary Sheet	9/51
P9-23	pH Worksheet	9/52
P9-24	Oil and Grease Worksheet (Gravimetric)	9/53
P9-25	Hardness Worksheet	9/54
P9-26	Chemical Oxygen Demand (COD) Worksheet	9/55
P9-27	Biochemical Oxygen Demand (BOD) Worksheet	9/56
P9-28	Bicarbonates and Carbonates Worksheet	9/57
P9-29	Adjustment for Water in Sample Worksheet	9/58
P9-30	Alkalinity/Total (Hot) Acidity Worksheet	9/59
P9-31	Atomic Absorption Dilution Factors Worksheet	9/60
P9-32	Atomic Absorption Data Worksheet	9/61
P9-33	Quality Control Summary Sheet - Metals	9/62
P9-34	Linear Regression for Total Organic Carbon Analysis	9/63
P9-35	TOC Soils by Ampule Method	9/64-65
P9-36	TOC Analysis Run Sheet	9/66
P9-37	Standardization Sheet forTOC Analysis	9/67
P9-38	TOC Analysis Summary	9/68
P9-39	TOC 700 Wet Weight Soil	9/69
P9-40	Percent Recovery TOC Soils	9/70
P9-41	TOC: Soil Analysis Summary	9/71
P9-42	QC TOC Water	9/72
P9-43	Run Sheets for TOX	9/73
P9-44	Calibration Sheet for TOX	9/74
P9-45	Cover Sheet TOX Water Analysis	9/75
P9-46	Cover Sheet TOX Soil Analysis	9/76



Section No. PO.0 Revision No.: 0

Date: April 5, 1988 Page 9 of 9

# LIST OF FIGURES (CONTINUED)

FIGURE NO.	TITLE	SECTION/PAGE
P9-47	Summary of TOX Results for Soils	9/77
P9-48	QC Sheet for TOX Soils	9/78
P9-49	QC Sheet for TOX Waters	9/79
P9-50	Summary for TOX Oils	9/80
P13-1	Sample Receiving Nonconformance Memo	13/2
P13-2	GC-GC/MS Nonconformance Memo	13/3
P13-3	Metals/Soils Nonconformance Memo	13/4-5
P13-4	General Chemistry Nonconformance Memo	13/6-7
P13-5	TOC/TOX Nonconformance Memo	13/8-9
P14-1	Quality Assurance/Quality Control In-House Audit	14/3-9
P16-1	Analytical Experience Chart	16/2
P16-2	Training Session Chart	16/3-10